



# PRICELIST SERVICES AND REPAIRS

V 10.1.2020

---

| <b>ANNUAL CHECK</b>  | Euro   |
|--|--------|
| Complete check incl. 2 replacement lines (items 1,2,3,4,5,6) | 195.00 |
| Special annual check – without line strength test            | 153.00 |
| Visual inspection after incident (items 4,5,6)               | 105.00 |

---

## CHECK PROCEDURES

|   |       |
|---|-------|
| (1) Porosity measurement                              | 19.00 |
| (2) Line strength test (not including replaced lines) | 53.00 |
| (3) Total line lengths                                | 79.00 |
| (4) Visual inspection of canopy                       | 69.00 |
| (5) Visual inspection of lines                        | 69.00 |
| (6) Visual inspection of connections                  | 21.00 |
| Lineset complete and replacement (see price list)     |       |

---

## REPAIRS

|                       |       |
|-----------------------|-------|
| Labour per man / hour | 69.00 |
|-----------------------|-------|

---

## REPAIR MATERIALS

|   |        |
|---|--------|
| Ripstop fabric / sq. m.                     | 14.00  |
| Adhesive Ripstop 6cm wide / m.              | 4.00   |
| Replacement line (each, excl. post)         | 14.00  |
| Replacement line (each, incl. installation) | 27.00  |
| Line per m. / up to 30 m                    | 2.00   |
| Line per m. / more than 30 m                | 1.50   |
| Test flight                                 | 120.00 |

---

## PACKING OF THE EMERGENCY RESERVE

|  |       |
|--|-------|
| Emergency reserve (square round) solo    | 60.00 |
| Emergency reserve (square round) biplace | 75.00 |
| Emergency reserve (cross canopy) solo    | 70.00 |
| Emergency reserve (cross canopy) biplace | 85.00 |
| Emergency reserve (stearable) solo       | 85.00 |
| Installation in harness                  | 20.00 |

---

## CANCELLATION

|   |       |
|---|-------|
| Fixed fee if check / repair has to be abandoned | 36.00 |
|---|-------|

---